

September 9, 1998

NDT Services, Inc.  
c/o Crossland Boilers Sales and Service, Inc.  
ATTN: Mr. Clarence David Vaughn, President  
Rio Cañas Industrial Park, Suite 370  
Road No. 175, Km. 0.02, Corner Road No. 1  
Caguas, PR 00726-4952

SUBJECT: NRC INSPECTION REPORT NO. 52-19438-01/98-05

Dear Mr. Vaughn:


This refers to the inspection conducted on August 19, 1998, at your Río Cañas Industrial Park facility. The purpose of the inspection was to determine whether security of licensed material was adequate. The inspection findings were discussed with you, at the end of the inspection on August 19, 1998. The enclosed report presents the results of this inspection.

The inspection examined activities for compliance with the Order dated March 27, 1998, which required among other things, placement of licensed material in secure storage. It included an examination of your storage area, inventory of licensed material (including radiographic devices) on your possession, interviews with personnel, and direct observations by the inspector.

The NRC's review of these matters is continuing, and no response to this letter is required at this time. We will notify you about our further deliberations on this case under separate correspondence.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, its enclosure and any response, if you choose to provide one, will be placed in the NRC Public Document Room.

454544



- NDT Services, Inc.

- 2

Should you have any questions concerning this letter, please contact me at  
(404) 562-4731.

Sincerely, -

original signed by M. Lesser

Mark S. Lesser, Chief  
Materials Licensing/Inspection Branch 2  
Division of Nuclear Materials Safety

Docket No. 030-17711  
License No. 52-19438-01

Enclosure: NRC Inspection Report  
No. 52-19438-01/98-05

cc w/enc]:  
Commonwealth of Puerto Rico

NDT Services, Inc.  
c/o Crossland Boilers Sales and Service, Inc.  
ATTN: Mr. Thomas Crossland, Owner  
Río Cañas Industrial Park, Suite 370  
Road No. 175, Km. 0.02, Corner Road No. 1  
Caguas, PR 00726-4952

Distribution w/enc]:

PUBLIC  
RII Docket File, DNMS  
C. Hosey  
M. Lesser  
H. Bermúdez  
W. McNulty  
A. Boland  
S. Hom

OFFICE	RII-DNMS				
SIGNATURE	<i>[Signature]</i>				
NAME	J. Velez				
DATE	9/9/98	9/ /98	9/ /98	9/ /98	9/ /98
COPY?	YES NO	YES NO	YES NO	YES NO	YES NO

OFFICIAL RECORD COPY

DOCUMENT FILENAME: G:\DNMS\MLIB2\NDT2.WPD

U.S. NUCLEAR REGULATORY COMMISSION  
REGION II

Docket No.: 030-17711

Report No.: 52-19438-01/98-05

Licensee: NDT Services. Inc.

Location: Caguas. Puerto Rico

Date: August 19. 1998

Inspector: José M. Díaz Vélez. Radiation Specialist  
Materials Licensing/Inspection Branch 2  
Division of Nuclear Materials Safety

Accompanied by: Ramón Torres. Remedial Project Manager-OSC  
Caribbean Environmental Protection Division  
U.S. Environmental Protection Agency

Approved by: Mark S. Lesser. Chief  
Materials Licensing/Inspection Branch 2  
Division of Nuclear Materials Safety

EXECUTIVE SUMMARY

NDT Services, Inc.  
NRC Inspection Report No. 52-19438-01/98-05

This announced special inspection included a review of licensee's security of material after the NRC issued an Order Suspending License (Effective Immediately) dated March 27, 1998. EA 98-108. The inspection included a walk-through of licensee facilities, a physical inventory of licensed material (including radiographic devices), interviews with personnel, and direct observations by the inspector.

The inspection confirmed that the licensee is not conducting licensed activities other than maintaining adequate security of licensed materials.

REPORT DETAILSSecurity of Material and Usage Statusa. Scope

The inspector reviewed the security of licensed materials after the NRC issued an Order Suspending License (Effective Immediately) dated March 27, 1998, EA 98-108.

b. Observations and Findings

The inspector conducted a walk-through of the licensee's facility and observed that licensed material was properly secured and in its designated storage area. The inspector determined that the building owner maintained a 24-hour security guard at the facility.

The inventory of radiography devices and sealed sources possessed by the licensee is as indicated in the table below.

Radiographic Exposure Devices (Cameras)				Sealed Sources			
NDT Device Number	Device Manufacturer	Device Model	Serial No.	Source Manufacturer	Source Model	Source Serial No.	Initial Activity (mCi)
PR-2	Amersham	660B	B2256	SPEC	T5	C41903	101.0
PR-3	Amersham	660B	B2255	SPEC	T5	CK2003	103.0
PR-4	Amersham	660B	B2254	SPEC	T5	DJ2401	108.0
PR-6	Amersham	660B	B2029	SPEC	T5	BF3002	073.0
PR-7	Amersham	660B	B2071	SPEC	T5	D41467	108.0
PR-8	Amersham	660B	B2072	SPEC	T5	DD0102	101.0
PR-1	Amersham (Tech/Ops)	402	72	n/a	n/a	n/a	n/a

No additional areas were inspected by the inspector. No violations of NRC regulatory requirements were identified by the inspector.

c. Conclusion

The licensee maintained proper security of licensed material. The licensee has maintained the radiographic devices in storage. No violations of NRC regulatory requirements were identified.

EXIT MEETING SUMMARY

An exit meeting was held with licensee representatives on August 19, 1998. The inspection confirmed that the licensee suspended the use, and maintained adequate security of licensed material. No proprietary information was received by the inspector.

## ATTACHMENT

1. LIST OF PERSONS CONTACTED  
C. Vaughn. Radiation Safety Officer. NDTSI.
2. INSPECTION PROCEDURES  
IP 87000 Licensed Materials Programs
3. LIST OF ITEMS OPENED. CLOSED. AND DISCUSSED  
None.
4. LIST OF ACRONYMS  
CFR Code of Federal Regulations  
EA Enforcement Action  
IP Inspection Procedure  
NRC Nuclear Regulatory Commission  
NDTSI NDT Services. Inc.